

Photo Log: <Soldotna Y Chevron>

Date of Inspection: 6/16/2014

Field	Commentary
Inspection Site	Soldotna Y Chevron – AK518
Location	Soldotna, AK
Date of Inspection	6/16/14
Inspectors	Ben Horwitz
Image IDs	Image Nos. 027, 028, 029
Original Work Type	Digital camera (jpg.)
Date of Digitization	7/3/14
Capture Device Used	Canon PowerShot SD750 with 12mm focal length
Image Optimization	In Microsoft Office Word 2007 Reduce size to x pixels

Figure 027.jpg: Turbine Sump for tank 4. Leak detector is missing and the pipe that was capped and left in place is visible.



Photo Log: <Soldotna Y Chevron>
Date of Inspection: 6/16/2014

Figure 028.jpg: Turbine Sump for tank 4. Leak detector is not present



Photo Log: <Soldotna Y Chevron>
Date of Inspection: 6/16/2014

Figure 029.jpg: Fill-pipe for tank 5

